

# PACSystems\* RX3i

## IC695RMX228-ACAB

GFK-2905B  
March 2016

### Redundancy Memory Xchange Module

The PACSystems\* Redundancy Memory Xchange (RMX) module operates as a node on a reflective memory network or as a dedicated link between CPUs in an RX3i Hot Standby CPU Redundancy system. When the RMX is not being used as a link in a redundancy system, it is functionally identical to the IC695CMX128 module. Each node in the network can be any reflective memory device that is compatible with the 5565 family. Whenever data is written to one node, all nodes on the network are automatically updated with the new data.

When used as a node on a reflective memory network, the RMX module provides deterministic sharing of data among PLCs and other computing devices on a high-speed fiber-optic network. A reflective memory network can contain up to 256 nodes.

Each node in the reflective memory network is connected in a daisy-chained loop using fiber-optic cables. The transmitter of the first node is tied to the receiver of the second. The transmitter of the second node is tied to the receiver of the third node, and so on, until the loop is completed at the receiver of the first node.

When used in a CPU redundancy system, the RMX modules provide a path for transferring data between the two redundancy CPUs in the redundant system. A complete communications path consists of one RMX in the primary unit, one RMX in the secondary unit, and two high-speed fiber-optic cables connecting them to each other. This must be a two-node ring: no other reflective memory nodes are allowed to be part of this fiber-optic network.

GE Intelligent Platforms **strongly recommends** two redundancy links (a total of four RMX modules) be configured and installed. Optionally, systems can be configured for a single redundancy link (a total of two RMX modules).

When the RMX is being used as link in a redundancy system, it cannot be used as a general-purpose Memory Xchange module. For details on the operation of a PACSystems CPU redundancy system, refer to GFK-2308, *PACSystems Hot Standby CPU Redundancy User's Manual*.

A PACSystems RX3i main rack supports a maximum of six Memory Xchange modules in any combination of RMX128, RMX228, and CMX128 modules. A maximum of two RMX modules can be configured as redundancy communication links.



## Features

- PACSystems RX3i single slot form factor.
- 128 Mbytes reflective memory.<sup>†</sup>
- Software configuration of all node parameters (no jumper or switch settings required).<sup>†</sup>
- High-speed easy-to-use 2.12 Gbaud fiber-optic network.
- No RX3i CPU processing required to operate the network.
- When not used in a Redundant pair, network-compatible with VMIC 5565 family of reflective memory devices, including the RX7i CMX/RMX module (hub required when mixing Multi Mode and Single mode modules on the same network).
- Connection with single-mode fiber up to 10 km/6.2 mi. A single mode card cannot directly connect to a multimode card.
- Dynamic packet sizes of 4 to 68 bytes, controlled by the RMX128/RMX228 module when configured to operate as a CMX128 module.
- Programmable module interrupt output.
- Four general-purpose network interrupts with 32 bits of data each.<sup>†o</sup>
- Network error detection.
- Up to 256 nodes per network.<sup>†</sup>
- Redundant transfer mode operation. This optional mode reduces the chance of a data packet being dropped from the network.<sup>†</sup>
- Configurable network memory offset allows you to assign nodes on a network to groups according to the 16MB segment in the network address space that they use.<sup>†</sup>

The RMX128/RMX228 module must be located in an RX3i Universal Backplane. The module can be hot-inserted and removed following the instructions in the *PACSystems RX3i System Manual* (GFK-2314).

<sup>†</sup> Not available when operating as a redundancy link in a CPU redundancy system.

## Specifications

Packet size	Dynamic, automatically controlled by RMX128/RMX228 module
User memory	128MB SDRAM
Input power (from RX3i power supply)	580 mA @ +3.3 VDC 220 mA @ +5 VDC
Connectors	<ul style="list-style-type: none"> <li>■ Fiber-optic LC type, conforms to IEC 61754-20</li> <li>■ Insertion loss: refer to cable/connector specifications</li> <li>■ Return loss: refer to cable/connector specifications</li> </ul>

Refer to the *PACSystems RX3i System Manual* (GFK-2314) for product standards and general specifications.

## Related Publications

Available at [www.ge-ip.com/support](http://www.ge-ip.com/support)

PACSystems CPU Reference Manual (GFK-2222)

PACSystems RX3i System Manual (GFK-2314E) or later

PACSystems Installation and Maintenance Requirements (GFK-2975) or later

PACSystems Memory Xchange Modules User's Manual (GFK-2300E) or later

PACSystems RX3i Ethernet NIU User's Manual (GFK-2439)

PACSystems Hot Standby CPU Redundancy User's Guide (GFK-2308J) or later

## Ordering Information

Description	Catalog Number
Reflective Memory Xchange Module for RX3i	IC695RMX228
Single Mode Fiber-optic Cables	Bought separately and not furnished by GE
Reflective Memory Hub	VMIACC-5595

## Installation and Maintenance

Refer to *PACSystems Installation and Maintenance Requirements* (GFK-2975) to ensure safe use guidelines are followed for each installation environment.

## Release History

Release	Firmware Version	Date	Comments
IC695RMX228-ACAB	HW -ACxx  2.01	March 2016	<b>Hardware change:</b> Power Cycle issue that in rare cases after cycling power on the module could result in "loss of module" during power up. A subsequent power cycle will clear this condition. Refer to the section <i>Problems Resolved by Hardware version -ACxx</i> for additional information.  <b>Firmware version 2.01:</b> In rare cases a timing issue occurs after a power cycle resulting in a "loss of module" during power up. A subsequent power cycle will clear this condition. Refer to the section <i>Problems Resolved by Firmware Release 2.01</i> for additional information.
IC695RMX228-ABAA	2.00	July 2015	Revision ABAA enhances the design's resistance to the rare condition of corruption during a memory read (seen by user as a broken redundant link on an RMX228) from occurring.
IC695RMX228-AAAA	2.00	June 2014	Initial release for IC695RMX228

## Important Product Information for this Release

### Upgrades



**Do not install firmware versions earlier than 2.00. This will render the unit inoperable and will require the unit be returned to the factory.**

### Functional Compatibility

The RMX requires the following versions for configuration and operation.

<b>Subject</b>	<b>Description</b>
<b>Programmer Version Requirements</b>	PME version 8.50 SIM2 or later must be used for compatibility with the RMX228 module.
<b>RX3i CPU</b>	RX3i CPU firmware version 8.15 (CI_R69431_2014_04_30_E3KL) or later is required to be used with the RMX228 module. PACSystems RX3i CRU320 is required for use in a redundancy system.
<b>RMX228 Versions</b>	Firmware versions earlier than 2.00 are not compatible with any of the RMX228 hardware versions.
<b>Rack Location</b>	The RMX128/RMX228 must be located in the main RX3i rack. IC695RMX128/RMX228 modules require a PCI backplane, which is not available on IC694CHSxxx expansion bases.

### Problems Resolved by Hardware version -ACxx

<b>Subject</b>	<b>Description</b>
<b>RMX does not always power up</b>	<p>Power Cycle issue that in rare cases after cycling power on the module could result in "loss of module" during power up. A subsequent power cycle will clear this condition. The fault we have seen when this issue occurs is as follows:</p> <pre> Group:4  LOSS_OTHR_MOD - Loss of or missing option module Error Code:94  Failure during module proxy initialization or startup Extra Data: 01 72 06 a2 80 08 0a 04 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 </pre> <p>This issue has been fixed with the -ACxx versions of the IC695RMX228</p>



***Operational Notes***

<b>Bad Data Interrupt</b>	To prevent continuous interrupts when the Bad Data Interrupt is enabled, you may want to temporarily set bit 8 in the LIER to 0 when a sync loss condition is detected. If your application is also using the Sync Loss Interrupt, you may also want to temporarily set bit 11 in the LIER to zero when the sync loss condition is detected. You can then re-enable the Bad Data Interrupt (and Sync Loss Interrupt if it was also disabled) when the sync loss condition has been corrected.
---------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------



1-800-433-2682

1-434-978-5100

[www.geautomation.com](http://www.geautomation.com)