PACSystems™ RX3i

GENIUS COMMUNICATIONS GATEWAY (IC695GCG001)





Important Product Information

	Fault reporting was enhanced for VersaMax remote I/O stations. VersaMax faults were			
	changed so that the fault extra data now provides a precise error code and rack, slot, and			
General	channel fault locators.			
Description	Faults from other types of Genius devices have not changed.			
	Hardware ID: IC695GCG001			
	Primary Firmware: Revision 3.1.4.0			
	PACSystems RX3i System Manual	GFK-2314		
Product Documentation	PACSystems RX3i Genius Communications Gateway Quick Start	GFK-2891		
	Guide			
	PACSystems RX3i Genius Communications Gateway User Manual	GFK-2892		
	PACSystems IC695GCG001 Genius Communications Gateway IPI	GFK-2900		

Release History

Catalog No.	Firmware Version	Date	Description
IC695GCG001-FH	3.1.4.0	Jul 2023	Fault reporting was enhanced for VersaMax remote I/O stations. VersaMax faults were changed so that the fault extra data now provides a precise error code and the rack, slot, and channel fault locators. This change is for VersaMax only. Faults from Series 90 Remote I/O, Genius blocks, and Field Control have not changed. Additional details can be found in GFK-2892H or later. In addition, the GSDML file for the GCG001 was updated to add additional error code definitions and to replace the GE branding.
IC695GCG001-EG	2.2.4.2	Aug 2022	The product's labels have been updated to show compliance with new certifications. For updated certifications, please refer to https://emerson-mas.force.com/communities/en_US/Article/Certifications-and-Agency-Approvals-Landing-Page
IC695GCG001-GG	2.2.4.2	Sep 2019	Following Emerson's acquisition of this product, changes have been made to apply appropriate branding and registration of the product with required certification agencies. No changes to material, process, form, fit or functionality.
IC695GCG001-DG	2.2.4.2	Mar 2019	Added Fault Status Data to the information that is produced by the GCG. Resolved two issues related to module placement in a VersaMax I/O drop. Resolved issue related to the selection of Genius IC660BBD100.

1

Catalog No.	Firmware Version	Date	Description
IC695GCG001-DF	2.2.3.2	Apr 2018	Improved output reinitialization behavior and incorrect fault reporting
IC695GCG001-DE	2.2.3.0	Jan 2018	Added support for Field Control, Outputs at Startup, and two COMMREQs. Also added RoHS compliance.
IC695GCG001-CD	2.0.1.0	Nov 2016	Product updated due to component obsolescence of internal serial flash memory device. Added WEEE symbol.
IC695GCG001-BD	2.0.1.0	Aug 2016	Removed the unused Genius B connector and the Bus B LED.
IC695GCG001-AD	2.0.1.0	Aug 2016	Adds support for the VersaMax Genius Network Interface, the IC660BBS101 isolated I/O block, and additional Genius baud rates. Fixes a problem with input data mapping for the IC660BBD120 High-Speed Counter.
IC695GCG001-AC	1.1.1.0	Feb 2016	Changed behavior of Genius Block circuit fault.
IC695GCG001-AB	1.1.0.4	Feb 2015	Fixes output glitch issues and adds enhancement to <i>Clear All Circuit Faults</i> COMMREQ.
IC695GCG001-AA	1.0.4.14	June 2014	Initial Release.

Firmware Updates/Upgrades

Upgrade Strategy	Units in the field are not upgradable to the D hardware revision. However, the firmware in all previous versions of IC695GCG001 is field-upgradable, using the firmware upgrade kit listed in this table. It is recommended that all devices be upgraded in this manner.
Upgrade Kit	IC695GCG001 Rel 2.2.4.2 Upgrade Kit 41G2015-MS10-000-A7.zip

New Features in this Release

Feature	Description		
Remote fault	Fault reporting was enhanced for VersaMax remote I/O stations. VersaMax faults were		
identification for IO	changed so that the fault extra data now provides a precise error code and the rack, slot, an		
in VersaMax GBI	channel fault locators. This change is for VersaMax only. Faults from Series 90 Remote I/O		
rack	Genius blocks, and Field Control have not changed.		
		Filename	Vendor Name
New version of	Previous release	GSDML-V2.3-GE-GENIUSGateway-	"GE Intelligent
GSDML File		20190219.xml	Platforms"
	New release	GSDML-V2.3-IntelligentPlatformsLLC- GENIUSGateway-20221106.xml	"Intelligent Platforms, LLC"

Issues Resolved in this Release

Feature enhancement release. This release added new functionality.

Functional Compatibility

Subject	Compatibility			
	CPE305/CPE310 Primary Firmware Release 8.15 or later			
	CPU315/CPU320 Primary Firmware Release 8.15 or later			
	CRU320 Primary Firmware Release 8.95 or later.			
	CPE330 Primary Firmw	are Release 8.90 or later. Release 9.21 or later is required to use the		
	new COMMREQs with the embedded PROFINET controller.			
	CPE400/CPL410 Primary Firmware Release 9.00 or later. Release 9.20 or later is required to use			
	the new COMMREQs with the embedded PROFINET controller			
Firmware Versions	All versions of the following CPUs are supported:			
	EPXCPE205			
	EPXCPE210			
	EPXCPE215			
	EPXCPE220			
	EPXCPE240			
	(Other CPU models are	a not supported)		
Drogrammer	·	nust import GSDML file)		
Programmer Version		r (GSDML file is included in PME install)		
Requirements GSDML Version	PIVIE 9.50 STIVI 14 OF TALE	PME 9.50 SIM 14 or later is required to resolve issues with the upgrade of GSDML files.		
	GSDML-V2.3-IntelligentPlatformsLLC-GENIUSGateway-20221106.xml			
Requirements	IC605DNC001 with firm	oware version 2.05 or later. Version 2.11 or later is required to use the		
	IC695PNC001 with firmware version 2.05 or later. Version 2.11 or later is required to use the new Clear All Circuit Faults feature introduced in Gateway version 1.1.0.4.			
RX3i PROFINET	Version 2.27 or later is required to use the Switch BSM and Enable/Disable Outputs			
Controller	COMMREQs introduced in Gateway version 2.2.3.0.			
	Version 3.11 or later is required to use the GCG with PROFINET Device IDs greater than 127.			
		/O devices are supported by the Genius Communications Gateway.		
	Do not connect other types of Genius devices to networks controlled by a Genius			
	Communications Gateway.			
	IC200GBI001	VersaMax Genius Network Interface Unit		
	IC660BBA020	24/48 Vdc 4-Input/2-Output Analog Block		
	IC660BBA021	24/48 Vdc RTD Input Block		
	IC660BBA023	24/48 Vdc Thermocouple Input Block		
	IC660BBA024	24/48 Vdc Current-Source Analog Block		
Genius I/O Devices	IC660BBA025	24/48 Vdc Current-Source Output Block		
Semas 2 o penees	IC660BBA026	24/48 Vdc Current-Source Input Block		
	IC660BBA100	115 Vac 4-Input/2-Output Analog Block		
	IC660BBA101	115 Vac RTD Input Block		
	IC660BBA103	115 Vac/125 Vdc Thermocouple Input Block		
	IC660BBA104	115 Vac/125 Vdc Current-Source Analog Block		
	IC660BBA105	115 Vac/125 Vdc Current-Source Output Block		
	IC660BBA106	115 Vac/125 Vdc Current-Source Input Block		
		·		
	1	I .		

	IC660BBD020/022	24/48 Vdc 16-Circuit Source I/O Blocks	
	IC660BBD021/023	24/48 Vdc 16-Circuit Sink I/O Blocks	
	IC660BBD024	12/24 Vdc 32-Circuit Source I/O Block	
	IC660BBD025	5/12/24 Vdc 32-Circuit Sink I/O Block	
	IC660BBD100	115 Vac 8-Circuit I/O Block	
	IC660BBD101	115 Vac Low-leakage 8-Circuit I/O Block	
	IC660BBD110	115 Vac 16-Circuit Input Block	
	IC660BBD120	High-Speed Counter	
	IC660BBR100	16-Circuit Normally-Closed Relay Block	
	IC660BBR101	16-Circuit Normally-Open Relay Block	
	IC660BBS100/102	115 Vac/125 Vdc Isolated I/O Blocks, with Failed Switch Diagnostics	
	IC660BBS101/103	115 Vac/125 Vdc Isolated I/O Block, without Failed Switch Diagnostics	
	IC660HHM501/502	Hand-Held Monitor	
	IC670GBI002/102	Field Control Genius Bus Interface Unit	
	IC697BEM733	Series 90-70 Remote I/O Scanner	
	When using the Gateway in a Hot Standby redundancy system, with older versions of the		
Hot-standby	CRU320 or CPE330 controllers, Genius I/O may not be scanned after a power cycle. This occurs		
Redundancy	if the primary controller is off and both the secondary Gateway and secondary controller are		
Reduitdancy	powered on at the same time. This problem is resolved in IC695CRU320 version 8.95 and later.		
	It is also resolved in IC695CPE330 version 8.90 and later.		
VersaMax Sub-	For firmware version 2	.0.1.0 the full IO capacity must be configured for VersaMax modules	
Module	Vmax_8_Channel_AI and Vmax_4_Channel_AO modules. With the GBC, you could configure a		
	subset of IO (for example for the Vmax_8_Channel_AI) you could configure (for example) 5 AI.		
Configuration	For the GCG, this is not currently possible and you must configure 8 AI.		
	Field Control is supported by the GCG beginning with version 2.2. Be advised that the full IO		
Field Control Sub-	capacity of its analog modules must be configured. For example, for the 8-channel Thermocouple Input module you must configure 48 points of Discrete Inputs, 8 channels of Analog Inputs, 16 points of Discrete Outputs, and 8 channels of Analog Outputs. Unused inputs		
Module			
Configuration			
	can be ignored. Unused outputs should be maintained at zero.		

Restrictions and Open Issues

Subject	Description
Discrete I/O Fault	If a discrete Genius block is configured so that all of its points are inputs or all of its
	points are outputs, the PROFINET Controller Module (PNC) may report a Valid Module
	Substitution fault in the I/O Fault Table. The block will operate as expected. The fault can
	be safely ignored.
Use of unsupported	When an IC695GCG001 is used to control a Genius I/O network, the presence of
Genius devices	unsupported Genius devices on the network can cause bus congestion, loss of fault
dernus devices	messages, and other undesirable operation.
Configuration of 8- and	When configuring 8-point and 32-point discrete Genius blocks in Machine Edition, you
32-point discrete blocks	must configure the block for both inputs and outputs. The Gateway does not support
5_ point allocated 2.000.0	input-only or output-only configurations for these devices.
Recurrence of a circuit	If the Hand-Held Monitor is used to clear a circuit fault, and that fault reappears at a
fault not shown in I/O	later time, no corresponding fault indication will appear in the I/O Fault Table. This
Fault Table	situation is resolved by using the <i>Clear Circuit Fault</i> or <i>Clear All Circuit Faults</i> COMMREQs
	rather than using the HHM.
Hand-Held Monitor does	When scanning the Genius bus with the Hand-Held Monitor, the scan will skip over the
not show the Gateway	Gateway and not show it, even though the Gateway is operating properly.
during a bus scan	
	In a scenario where the user does not configure a GCG at bus address 30 or 31, stores
GCG Configuration	that configuration to the PLC, then corrects the configuration by adding a GCG at bus
	address 30 or 31, the GCG may not scan I/O on its Genius bus. This is resolved by power-cycling the GCG.
	If a Genius I/O device is on the bus at bus address 30, but it does not match the PME
	hardware configuration, no fault will be logged in the I/O Fault Table. The device will
SBA 30 Faults	remain in Outputs Disabled state. Its status bit and point fault contacts will all be OFF.
3B/(30 Taalts	This can be corrected by using the correct Genius device or by changing the PME
	configuration so that it matches the actual network configuration.
	Occasionally, after hardware configuration is stored to a PLC that controls a Genius
	Gateway, it can take up to 20 seconds for the Gateway to begin showing active status
Start-up Delay	and transferring I/O data. This occurs on lightly loaded buses (2 I/O devices) when the
	Gateway is controlled by the embedded PROFINET controller in a CPE330 or CPE400.
	This problem can be worked-around by (1) using a PNC001, instead of the embedded
	controller or (2) spread out the assigned bus addresses of the Genius devices, instead of
	using consecutive or near-by bus addresses. That is, put a gap of 8 or more addresses
	between the devices' addresses.

Operational Notes

Subject	Description		
Add/Loss Faults	Beginning with version 2.2.3.0 of the Genius Gateway, Addition of Module and Loss of		
	Module faults are not created in the I/O Fault Table when a Genius device comes on the		
	Genius bus or leaves the Genius bus. To know when a device is added or lost, the user		
	should monitor the states of the Gateway's 32 Genius Status bits.		
	In PAC Machine Edition (PME), when a Gateway is upgraded from an older GSDML file		
	(prior to 2016) to the 20160818 version or later, if there are any Genius High-Speed		
	Counter blocks in the configuration, PME displays a Conflicts List window indicating that		
IC660BBD120 High-	the input references have been given new values. When this occurs, take note of the		
Speed Counter	existing reference addresses and press the Proceed button. Then open the hardware		
	configuration for the High-Speed Counter module. If either of the %I or %AI reference		
	addresses were changed, change them back to their original values. This is a one-time		
	operation per High-Speed Counter.		
	Firmware version 1.1.1.0 changes the behavior of the GCG when a Genius Block circuit		
	fault occurs. In firmware versions 1.1.04 and earlier, a circuit fault would result in all I/O		
	points on the Genius Block indicating a faulted condition. With firmware version 1.1.1.0		
	and later, when a circuit fault occurs on a Genius Block only the I/O point where the		
	circuit fault occurred will be faulted.		
Fault Contact Operation	Fault Contact Operation with FW 1.1.1.0 and Later:		
rault Contact Operation	When a circuit fault occurs on a discrete block or a channel fault occurs on an analog		
	block, none of the block's <u>fault contacts</u> will energize. The only indicators of the presence		
	of a circuit fault are an entry in the I/O Fault Table the Fault LED on the Gateway, and the		
	Fault LED on the faulted Genius block itself.		
	Prior to FW version 1.1.1.0 all of the fault contacts associated with the faulted Genius		
	block would energize.		
	Genius bus address 0 is not available for configuration of Genius devices in PAC Machine		
Bus Address 0	Edition (PME). The only Genius device that can be used at bus address 0 is the Hand-Held		
	Monitor.		
Bus Addresses 30 and 31	The Gateway can be assigned to bus addresses 30 and 31 only. Do not configure the		
	Gateway to both addresses 30 and 31 simultaneously. Doing so will cause the Genius		
	bus to operate in an unexpected manner.		
	The Genius Communications Gateway supports Simple Network Management Protocol		
SNMP	(SNMP). However, requests directed to the device must use the community name		
	"Emerson".		

General Contact Information

Home link: http://www.emerson.com/industrial-automation-controls

Knowledge Base: https://www.emerson.com/industrial-automation-controls/support

Technical Support

Americas

Phone: 1-888-565-4155

1-434-214-8532 (If toll free option is unavailable)

Customer Care (Quotes/Orders/Returns): customercare.mas@emerson.com

Technical Support: support.mas@emerson.com

Europe

Phone: +800-4444-8001

+420-225-379-328 (If toll free option is unavailable)

+39-0362-228-5555 (from Italy - if toll-free 800 option is unavailable or dialing from a

mobile telephone)

Customer Care (Quotes/Orders/Returns); customercare.emea.mas@emerson.com

Technical Support: support.mas.emea@emerson.com

Asia

Phone: +86-400-842-8599

+65-6955-9413 (All other Countries)

Customer Care (Quotes/Orders/Returns): customercare.cn.mas@emerson.com

Technical Support: support.mas.apac@emerson.com

Any escalation request should be sent to mas.sfdcescalation@emerson.com

Note: If the product is purchased through an Authorized Channel Partner, please contact the seller directly for any support.

Emerson reserves the right to modify or improve the designs or specifications of the products mentioned in this manual at any time without notice. Emerson does not assume responsibility for the selection, use, or maintenance of any product. Responsibility for proper selection, use, and maintenance of any Emerson product remains solely with the purchaser.

© 2023 Emerson. All rights reserved. Emerson Terms and Conditions of Sale are available upon request. The Emerson logo is a trademark and service mark of Emerson Electric Co. All other marks are the property of their respective owners.

